



Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021 Issue: A1 Date: 17.07.2023 TCDS: EASA.A.642
Service Bulletin			

B23 Approved Publications (AFM, AMM, SB)
SERVICE BULLETIN

<p>Office of Airworthiness release</p> <p>Date:</p> <p>Name: B. Kölmel</p> <p>Signature:</p>

<p>Verification Engineer</p> <p>I hereby declare that the technical content of this document is correct and can be used to fulfil the obligations of the type design holder per 21.A.265(h)</p> <p>Date:</p> <p>Name: E. v.d. Snoek</p> <p>Signature:</p>
--

<p>Author</p> <p>Date:</p> <p>Name: M. Basien</p> <p>Signature:</p>
--

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021 Issue: A1 Date: 17.07.2023 TCDS: EASA.A.642
Service Bulletin			

Amendments

Issue	Reason	Date
A	Initial issue (DC-079, -083, -091, -095)	20.03.2023
A1	Update due to SB-035 (DC-099), SB-024 (DC-101), SB-033 (DC-096), SB-034 & 001-AMM (DC-097), SB-036 (DC-100)	17.07.2023

B23 Approved Publications (AFM, AMM, SB)

This service bulletin informs operators and maintenance organizations with respect to the approved publications for the B23 aircraft type. These are:

- AFM Airplane flight manual
- AMM Airplane maintenance manual
- SB Service bulletin

STANDARD


0 General

0.1 ATA Code

ATA 00 GENERAL

0.2 Effectivity

All serial numbers of Bristell B23 TCDS EASA.A.642

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021 Issue: A1 Date: 17.07.2023 TCDS: EASA.A.642
Service Bulletin			

1 Planning information

1.1 Reason

This service bulletin is published and re-issued whenever any of the relevant publications is affected.

The specific reason for each issue is listed in the amendment sheet on page 1 referring to respective design change processes which are identified by numbers “ADxC-73-DC-xx” respectively abbreviated as “DC-xx”.

1.2 Safety Intent

The safety intent is N/A.

Note: the content of specific changes might as well introduce additional safety relevant publications or changes to those in which case specific SB’s are issued for mandatory implementation.

1.3 Configuration Description

No technical configuration change is implemented by this Service Bulletin.

Applicable configuration of AMM and AFM for specific variants and versions for the B23 is listed in this section

Note: the initial aircraft configuration (as manufactured by POA), respectively the initially installed design changes, are stated in the appendix to the respective Form 52 issued for the aircraft SN.


Legend for the following tables

X = publication is part of the configuration

DC-[xx] = publication is part of the configuration “if installed”

- = publication is not part of the configuration


AFM/AMM and supplements affecting individual manufacturing serial numbers are not listed.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr:	ADxC-73-SB-021
			Issue:	A1
			Date:	17.07.2023
			TCDS:	EASA.A.642
Service Bulletin				

1.3 continued

Publication	Variant → Edition/Date	B23	B23-915	¹ B23- 912-G500	¹ B23-915-G500	Topic
Airplane maintenance manual ADxC-73-.....						
001-AMM	2.1 / 31.05.2023	X	X	X	X	basic
Airplane maintenance manual supplement ADxC-73-.....						
003-AMM	1.1 / 23.02.2023	-	X	-	X	915
004-AMM	1.0 / 28.01.2021	DC-004	-	-	-	AT-1
010-AMM	1.0 / 24.02.2021	DC-010	-	-	-	Water heater
012-AMM	1.0 / 14.06.2021	DC-012 DC-019	-	-	-	Silencer
020-AMM	1.0 / 01.02.2022	-	DC-020	-	-	GNX375
023-AMM	1.0 / 19.07.2021	DC-023	DC-023	DC-023	DC-023	CO sensor
025-AMM	1.0 / 18.07.2022	-	DC-025	-	-	Tow winch
036-AMM	1.0 / 18.02.2022	DC-036	-	-	-	GNX375
037-AMM	1.0 / 18.02.2022	DC-037	-	-	-	DME
038-AMM	1.0 / 11.02.2022	DC-038	-	-	-	GMC507
039-AMM	1.0 / 20.03.2022	-	DC-039	-	-	GMC507
044-AMM	1.0 / 04.04.2022	-	DC-044	-	-	GI275
047-AMM	1.0 / 31.03.2022	-	DC-047+ (DC-044+ DC-039)	-	-	AT-1
049-AMM	1.2 / 23.02.2023	-	-	-	X	G500
053-AMM	1.0 / 16.08.2022	-	DC-053	-	-	GTN650
070-AMM	1.1 / 23.02.2023	-	-	X	-	G500
076-AMM	1.0 / 20.03.2023	-	-	-	DC-076 (DC-025)	Tow winch


¹ Formally this is not a variant in the TCDS but handled accordingly in anticipation of IFR variant using the same avionic system.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr:	ADxC-73-SB-021
			Issue:	A1
			Date:	17.07.2023
			TCDS:	EASA.A.642
Service Bulletin				

1.3 continued

Variant →		B23	B23-915	² B23-912-G500	² B23-915-G500	Topic
Publication	Edition/Date					
Airplane flight manual ADxC-73-.....						
001-AFM	B3 / 12.06.2023	X	-	-	-	basic
003-AFM	B2 / 23.02.2023	-	X	-	-	915
070-AFM	A2 / 17.07.2023	-	-	X	-	912-G500
049-AFM	B1 / 23.02.2023	-	-	-	X	915-G500
Airplane flight manual supplement ADxC-73-.....						
003-2-AFM	A1 / 23.02.2023	-	DC-003-2	-	-	towing
004-AFM	A1 / 23.02.2023	DC-004	-	-	-	AT-1 / h-counter
010-AFM	A1 / 23.02.2023	DC-010	-	DC-010	-	Water heater
012-AFM	A1 / 23.02.2023	DC-012	-	DC-012	-	Silencer
020-AFM	A1 / 23.02.2023	-	DC-020	-	-	GNX375
023-AFM	A1 / 23.02.2023	DC-023	DC-023	DC-023	DC-023	CO sensor
025-AFM	A / 19.07.2022	-	DC-025	-	-	Tow winch
036-AFM	A1 / 23.02.2023	DC-036	-	-	-	GNX375
037-AFM	A1 / 23.02.2023	DC-037	-	-	-	DME
038-AFM	A1 / 23.02.2023	DC-038	-	-	-	GMC507
039-AFM	A / 02.03.2022	-	DC-039	-	-	GMC507
044-AFM	A / 04.04.2022	-	DC-044	-	-	GI275
047-AFM	A1 / 23.02.2023	-	DC-047+ (DC-039+ DC-044)	-	-	AT-1
053-AFM	A / 08.07.2022	-	DC-053	-	-	GTN650
076-AFM	A / 20.03.2022	-	-	-	DC-076 (DC-025)	Tow winch


² Formally this is not a variant in the TCDS but handled accordingly in anticipation of IFR variant using the same avionic system.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021
			Issue: A1
			Date: 17.07.2023
			TCDS: EASA.A.642
Service Bulletin			


1.3 continued

Publication	Edition/Date	Title/Remark	Variant →	B23	B23-915	³ B23-912-G500	³ B23-915-G500
Service Bulletin ADxC-73-.....							
SB-001	A / 14.01.2021	editorial change AFM / no longer relevant due to issue SB-021		SN006/2020 SN007/2020 SN012/2020 SN022/2020	-	-	-
SB-002	A / 21.01.2021	Change to AMM elevator tolerances and update of figure / no longer relevant due to issue SB-021		SN006/2020 SN007/2020 SN012/2020 SN022/2020	-	-	-
SB-003	A / 29.01.2021	OPTIONAL Implementation of DC-004 hour meter and/or FLARM		All	-	-	-
SB-004	A / 24.02.2021	OPTIONAL Implementation of DC-010 DEFA water heater		All	-	All	-
SB-005	A / 14.06.2021	OPTIONAL Implementation of DC-012 silencer system		All	-	All	-
SB-006	-	<i>deleted</i>		-	-	-	-
SB-007	A1 / 23.02.2023	OPTIONAL Implementation of DC-023 CO sensor		All			
SB-008	A / 13.08.2021	Change of AFM; DC-029 / no longer relevant due to issue SB-021		All without DC-029	-	-	-
SB-009	-	<i>reserved</i>		-	-	-	-
SB-010	A / 10.11.2021	OPTIONAL Implementation of DC-033 safety equipment provisions		All			
SB-011	-	<i>reserved</i>					
SB-012	A / 18.02.2022	Replacement of wheel pant brackets		All without DC-040			


³ Formally this is not a variant in the TCDS but handled accordingly in anticipation of IFR variant using the same avionic system.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021
			Issue: A1
			Date: 17.07.2023
			TCDS: EASA.A.642
Service Bulletin			

Publication	Edition/Date	Title/Remark	Variant →			
			B23	B23-915	³ B23-912-G500	³ B23-915-G500
Service Bulletin ADxC-73-.....						
SB-013	A / 11.04.2022	replacement of fuel filler neck placard	-	All without DC-042	-	-
SB-014	A / 21.04.2022	replacement of fuel filler neck placard	All without DC-042	-	-	-
SB-015	A / 26.08.2022	OPTIONAL replacement of oil cooler DC-045	All	-	All	
SB-016	A / 20.09.2022	OPTIONAL Sliding window retrofit DC-052	All			
SB-017	A / 14.11.2022	Interchange wiring of GNC255 and GTN650 DC-058	-	-	-	All without DC-058
SB-018	A / 14.10.2022	Additional riveting of sleeve attachment of AP roll servo rod	All without DC-062			
SB-019	A / 20.09.2022	Editorial change AFM / no longer relevant due to issue SB-021	All without DC-064			
SB-020	A / 09.01.2023	mass balance and bolt (DC-061)	All without DC-061 or DC-092	-	All without DC-061 or DC-092	-
SB-021	A1 / 17.07.2023	Approved Publications (AFM, AMM, SB)	All			
SB-022	-	<i>reserved</i>	-	-	-	-
SB-023	A / 10.01.2023	OPTIONAL Installation glare shield with handles (DC-067)	All			
SB-024	B / 20.06.2023	Approved Software	All			
SB-025	A / 06.03.2023	Installation governor for ROTAX 915iS engines (DC-072)	-	-	-	-
SB-026	-	<i>deleted</i>	-	-	-	-
SB-027	-	<i>reserved</i>	-	-	-	-
SB-028	-	<i>deleted</i>	-	-	-	-

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021
			Issue: A1
			Date: 17.07.2023
			TCDS: EASA.A.642
Service Bulletin			

Publication	Edition/Date	Title/Remark	Variant →			
			B23	B23-915	³ B23-912-G500	³ B23-915-G500
Service Bulletin ADxC-73-.....						
SB-029	A / 09.01.2023	mass balance and bolt (DC-092)	All without DC-061 or DC-092	-	-	-
SB-030	A / 14.02.2023	Installation registration plate Type (France + Switzerland)	All			
SB-031	A / 14.02.2023	Installation registration plate Type (Germany)	All			
SB-032	A / 24.02.2023	Beringer brake calliper seal replacement (DC-094)	All			
SB-033	A / 22.05.2023	Chafing-protection of seat bracket (DC-096)	All without DC-096			
SB-034	A / 31.05.2023	Propeller mounting inspection (DC-097)	All without DC-097			
SB-035	A / 17.07.2023	Avoid engine stress ROTAX 912	All	-	All	-
SB-036	A / 27.06.2023	Update tow winch system installation	-	All with DC-025 or -076	-	-

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021 Issue: A1 Date: 17.07.2023 TCDS: EASA.A.642
Service Bulletin			

1.4 Compliance

If criteria in Section 0 is met

- Service bulletin must be accomplished
 - This SB could be made mandatory by an EASA AD.
 - This SB is mandatory as per EASA AD no. xyxyx
- Service bulletin recommended to be accomplished to prevent significant operational disruptions
- Service bulletin to introduce improvements
- Service bulletin for convenience or option

Compliance time is at each scheduled and unscheduled maintenance action.

1.5 Approval statement

The technical content of this document is approved under the authority of the DOA ref. EASA. 21J.411.

1.6 Concurrent publications N/A

1.7 Manpower

Approx. 0.25 hour is required to accomplish this SB.

1.8 Weight and Balance N/A


1.9 Electrical load data N/A

1.10 Software modification N/A

Note: for approved Software refer to ADxC-73-SB-024 latest revision

1.11 Referenced documentation N/A

1.12 Other publications effected N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021 Issue: A1 Date: 17.07.2023 TCDS: EASA.A.642
Service Bulletin			

2 Material information

2.1 Material- cost – availability N/A

2.2 Company support information

Affected publications can be ordered from

BRM AERO, s.r.o.

Address: Letecká 255 686 04 Kunovice Czech Republic

Phone: + 420 773 984 338

E-mail 1: info@brmaero.com

E-mail 2: aero.brm@gmail.com

Web: <http://www.brmaero.com>

or downloaded from

<https://www.bristell.com/bulletins/>

respectively from


<https://www.bristell.com/technical-documentation/>

For the latter login credentials must be ordered form BRM Aero, s.r.o.

2.3 Material requirements per aircraft N/A

2.4 Rework parts N/A

2.5 Special tooling N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		B23 Approved Publications (AFM, AMM, SB)	Doc-Nr: ADxC-73-SB-021 Issue: A1 Date: 17.07.2023 TCDS: EASA.A.642
Service Bulletin			

3 Accomplishment/Instructions

- 1) Check airplane AFM and supplements for currency, update if needed
- 2) Check airplane AMM and supplements for currency, update if needed
- 3) Check airplane SB compliance status
- 4) Make a log book entry and add note to aircraft CAW documentation that this Service bulletin has been incorporated.

4 Appendix

NIL