

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Bristell B23	Doc-Nr: ADxC-73-SB-019 Issue: A Date: 20.09.2022 Change-no.: ADxC-73-DC-064
Service Bulletin			

Bristell B23
SERVICE BULLETIN

<p>Office of Airworthiness release</p> <p>Date:</p> <p>Name:</p> <p>Signature:</p>

<p>Verification Engineer</p> <p>I hereby declare that the technical content of this document is correct and can be used to fulfil the obligations of the type design holder per 21.A.265(h)</p> <p>Date:</p> <p>Name:</p> <p>Signature:</p>
--

<p>Author</p> <p>Date:</p> <p>Name: Eric van der Snoek</p> <p>Signature:</p>

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Bristell B23	Doc-Nr: ADxC-73-SB-019 Issue: A Date: 20.09.2022 Change-no.: ADxC-73-DC-006
Service Bulletin			


Amendments

Issue	Reason	Date
A	Initial issue	20.09.2022

<p>Bristell B23</p> <p>Editorial change of the AFM as described in ADxC-73-DC-064:</p> <p>For model Bristell B23: Update cabin smoke procedure. Editorial endorsement of fuel type. Update of Carburettor heat use in normal procedures. List of supplements.</p> <p>For model Bristell B23-915: Updated cabin smoke procedure. Minor corrections.</p>
--

STANDARD

0 General
0.1 ATA Code ATA 00 General ATA 25 EQUIPMENT/FURNISHINGS – AFM replacement
0.2 Effectivity All serial numbers of Bristell B23 and Bristell B23-915 TCDS EASA.A.642

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Bristell B23	Doc-Nr: ADxC-73-SB-019 Issue: A Date: 20.09.2022 Change-no.: ADxC-73-DC-006
Service Bulletin			

1 Planning information

1.1 Reason

Implementation of the revised flight manual.

1.2 Safety Intent

N/A – editorial change.

1.3 Configuration Description

No technical configuration change.

The current revision of the AFM is furnished to the SN mentioned in Section 0 with this SB.

1.4 Compliance

If criteria in Section 0 is met

- Service bulletin must be accomplished
- This SB could be made mandatory by an EASA AD.
 - This SB is mandatory as per EASA AD no. _____
 - Service bulletin recommended to be accomplished to prevent significant operational disruptions
 - Service bulletin to introduce improvements
 - Service bulletin for convenience or option

Compliance time is within the next 25hrs of operation.

1.5 Approval statement


The technical content of this document is approved under the authority of the DOA ref. EASA. 21J.411.

1.6 Concurrent publications

For model Bristell B23: ADxC-73-001-AFM issue B1 issue date 16.09.2022
For model Bristell B23-915: ADxC-73-003-AFM issue B1 issue date 16.09.2022

1.7 Manpower


Approx. 0.25 hours are required to accomplish this SB.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Bristell B23	Doc-Nr: ADxC-73-SB-019 Issue: A Date: 20.09.2022 Change-no.: ADxC-73-DC-006
Service Bulletin			

- 1.8 Weight and Balance N/A
- 1.9 Electrical load data N/A
- 1.10 Software modification N/A
- 1.11 Referenced documentation

For model Bristell B23: ADxC-73-001-AFM issue B1 issue date 16.09.2022
 For model Bristell B23-915: ADxC-73-003-AFM issue B1 issue date 16.09.2022

- 1.12 Other publications effected N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Bristell B23	Doc-Nr: ADxC-73-SB-019 Issue: A Date: 20.09.2022 Change-no.: ADxC-73-DC-006
Service Bulletin			

2 Material information

- 2.1 Material- cost – availability N/A
- 2.2 Company support information N/A
- 2.3 Material requirements per aircraft N/A
- 2.4 Rework parts N/A
- 2.5 Special tooling N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Bristell B23	Doc-Nr: ADxC-73-SB-019 Issue: A Date: 20.09.2022 Change-no.: ADxC-73-DC-006
Service Bulletin			

3 Accomplishment/Instructions

For model Bristell B23:

- 1) Note revised pages in section *0.2 List of Effective Pages* in ADxC-73-001-AFM issue B1.
- 2) Remove these pages of the current ADxC-73-001-AFM from aircraft.
- 3) Supply the revised pages from current issue of ADxC-73-001-AFM issue B1.
- 4) Make a log book entry and add note to aircraft CAW documentation that this Service bulletin has been incorporated.

For model Bristell B23-915:

- 1) Note revised pages in section *0.2 List of Effective Pages* in ADxC-73-003-AFM issue B1.
- 2) Remove these pages of the current ADxC-73-003-AFM from aircraft.
- 3) Supply the revised pages from current issue of ADxC-73-003-AFM issue B1.

Make a log book entry and add note to aircraft CAW documentation that this Service bulletin has been incorporated.

4 Appendix N/A