

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation glare shield with handles (DC-067)	Doc-Nr: ADxC-73-SB-023 Issue: A Date: 10.01.2023 ChangeNr.: ADxC-DC-73-067
Service Bulletin			

Installation glare shield with handles (DC-067)  
SERVICE BULLETIN

<p><b>Office of Airworthiness release</b></p> <p>Date:</p> <p>Name: [Released by]</p> <p>Signature:</p>
---

<p><b>Verification Engineer</b></p> <p>I hereby declare that the technical content of this document is correct and can be used to fulfil the obligations of the type design holder per 21.A.265(h)</p> <p>Date:</p> <p>Name: [Checked by]</p> <p>Signature:</p>
---

<p><b>Author</b></p> <p>Date:</p> <p>Name: Andre von Pinkowski</p> <p>Signature:</p>
--

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation glare shield with handles (DC-067)	Doc-Nr: ADxC-73-SB-023 Issue: A Date: 10.01.2023 ChangeNr.: ADxC-DC-73-067
Service Bulletin			

## Amendments

Issue	Reason	Date
A	Initial issue	10.01.2023

### Installation glare shield with handles (DC-067)

DC-067 introduced the option of glare shield with handles in production. By this SB, this option is made available for retrofit.

STANDARD

#### 0 General

##### 0.1 ATA Code

ATA 25 EQUIPMENT/FURNISHINGS – Glareshield

##### 0.2 Effectivity

All B23 models

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation glare shield with handles (DC-067)	Doc-Nr: ADxC-73-SB-023 Issue: A Date: 10.01.2023 ChangeNr.: ADxC-DC-73-067
Service Bulletin			

## 1 Planning information

### 1.1 Reason

Optional replacement of original glare shield with glare shield with handle.

### 1.2 Safety Intent

The safety intent is N/A.

### 1.3 Configuration Description

If criteria in Section 0 met, change the glareshield by glareshield with handles as an option.

Specify colour of glare shield, which, for reason of night compatibility, must be matched with the colour of the cockpit.

-charcoal / 15063

-ambassador black / 15100

Contact BRM Aero to clarify.

### 1.4 Compliance

If criteria in Section 0 is met

- Service bulletin must be accomplished
- This SB could be made mandatory by an EASA AD.
  - This SB is mandatory as per EASA AD no. xyxyx
  - Service bulletin recommended to be accomplished to prevent significant operational disruptions
  - Service bulletin to introduce improvements
  - Service bulletin for convenience or option

### 1.5 Approval statement

The technical content of this document is approved under the authority of the DOA ref. EASA. 21J.411.

### 1.6 Concurrent publications N/A

### 1.7 Manpower

Approx. 0.5 hour is required to accomplish this SB.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation glare shield with handles (DC-067)	Doc-Nr: ADxC-73-SB-023 Issue: A Date: 10.01.2023 ChangeNr.: ADxC-DC-73-067
Service Bulletin			

- 1.8 Weight and Balance N/A
- 1.9 Electrical load data N/A
- 1.10 Software modification N/A
- 1.11 Referenced documentation N/A
- 1.12 Other publications effected N/A

## 2 Material information

### 2.1 Material- cost – availability N/A

Contact BRM Aero.

### 2.2 Company support information

**BRM AERO, s.r.o.**

Address: Letecká 255 686 04 Kunovice Czech Republic

Phone: + 420 773 984 338

E-mail 1: info@brmaero.com

E-mail 2: aero.brm@gmail.com

Web: <http://www.brmaero.com>

### 2.3 Material requirements per aircraft

If criteria from Section 0 is met, replace original glareshield 25B200009N N by glareshield with handles.

Assembled glareshield with handles - **25B201009N**

Fasteners are reused.

### 2.4 Rework parts N/A

### 2.5 Special tooling N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation glare shield with handles (DC-067)	Doc-Nr: ADxC-73-SB-023 Issue: A Date: 10.01.2023 ChangeNr.: ADxC-DC-73-067
Service Bulletin			

### 3 Accomplishment/Instructions

- 1) Dismount and remove original glare shield.
- 2) Install glare shield lights connection and air duct connection. Mount new (assembled) glare shield.
- 3) Check function of glareshield lights.
- 4) Make a log book entry and add note to aircraft CAW documentation that this Service bulletin has been incorporated.

## 4 Appendix

