



Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation governor for ROTAX 915iS engines	Doc-Nr: ADxC-73-SB-025 Issue: A Date: 06.03.2023 ChangeNr.: ADxC-DC-73-072
Service Bulletin			

Installation governor for ROTAX 915iS engines
SERVICE BULLETIN

<p>Office of Airworthiness release</p> <p>Date:</p> <p>Name: Kölmel</p> <p>Signature:</p>
--

<p>Verification Engineer</p> <p>I hereby declare that the technical content of this document is correct and can be used to fulfil the obligations of the type design holder per 21.A.265(h)</p> <p>Date:</p> <p>Name: Kölmel</p> <p>Signature:</p>

<p>Author</p> <p>Date:</p> <p>Name: Andre von Pinkowski</p> <p>Signature:</p>
--

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation governor for ROTAX 915iS engines	Doc-Nr: ADxC-73-SB-025 Issue: A Date: 06.03.2023 ChangeNr.: ADxC-DC-73-072
Service Bulletin			

Amendments


Issue	Reason	Date
A	Initial issue	06.03.2023

Installation governor for ROTAX 915iS engines

Change of governor part number. No technical change.

STANDARD

0 General
0.1 ATA Code ATA 76 ENGINE CONTROLS – Propeller governor
0.2 Effectivity All B23 models, equipped with ROTAX 915iSc3 A engines.

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation governor for ROTAX 915iS engines	Doc-Nr: ADxC-73-SB-025 Issue: A Date: 06.03.2023 ChangeNr.: ADxC-DC-73-072
Service Bulletin			

1 Planning information

1.1 Reason

Changed part number of propeller governor from P-110-030/A to P-110-056/A.

1.2 Safety Intent

The safety intent is N/A.

1.3 Configuration Description N/A

1.4 Compliance

If criteria in Section 0 is met

- Service bulletin must be accomplished
 - This SB could be made mandatory by an EASA AD.
 - This SB is mandatory as per EASA AD no. xyxyx
- Service bulletin recommended to be accomplished to prevent significant operational disruptions
- Service bulletin to introduce improvements
- Service bulletin for convenience or option

1.5 Approval statement

The technical content of this document is approved under the authority of the DOA ref. EASA. 21J.411.

1.6 Concurrent publications N/A

1.7 Manpower N/A

No change of maintenance procedure.


1.8 Weight and Balance N/A

1.9 Electrical load data N/A

1.10 Software modification N/A

1.11 Referenced documentation N/A

1.12 Other publications effected N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation governor for ROTAX 915iS engines	Doc-Nr: ADxC-73-SB-025 Issue: A Date: 06.03.2023 ChangeNr.: ADxC-DC-73-072
Service Bulletin			

2 Material information

2.1 Material- cost – availability N/A

2.2 Company support information N/A

BRM AERO, s.r.o.

Address: Letecká 255 686 04 Kunovice Czech Republic

Phone: + 420 773 984 338

E-mail 1: info@brmaero.com

E-mail 2: aero.brm@gmail.com


Web: <http://www.brmaero.com>

2.3 Material requirements per aircraft

Jihostroj P-110-056/A , request at BRM

2.4 Rework parts N/A

2.5 Special tooling N/A

Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Installation governor for ROTAX 915iS engines	Doc-Nr: ADxC-73-SB-025 Issue: A Date: 06.03.2023 ChangeNr.: ADxC-DC-73-072
Service Bulletin			

3 Accomplishment/Instructions

- 1) If criteria from Section 0 and the old propeller governor, p/n: Jihostroj P-110-**030**/A, needs to be replaced, request propeller governor, p/n: Jihostroj P-110-**056**/A from BRM Aero.
- 2) Check max engine RPM on ground run, which must be 5780RPM \pm 20RPM at full throttle.
- 3) Make a log book entry and add note to aircraft CAW documentation that this Service bulletin has been incorporated.

Aircraft Design
Certification GmbH
Reichensteinstr.48
69151 Neckargemünd



Installation governor
for ROTAX 915iS
engines

Doc-Nr: ADxC-73-SB-025
Issue: A
Date: 06.03.2023
ChangeNr.: ADxC-DC-73-072

Service Bulletin

4 Appendix

NIL