


Aircraft Design Certification GmbH Reichensteinstr.48 69151 Neckargemünd		Engine Mass Ballast	Doc-Nr: ADxC-73-SB-020 Issue: B Date: 10.10.2023 ChangeNr.: ADxC-73-DC-105
Service Bulletin Bristell B23			

Amendments

Issue	Reason	Date
Draft	EASA comments	09.10.2022
A	First Issue	09.01.2023
B	Cancellation, ref. ADxC-73-SB-029 issue B	10.10.2023

<p style="text-align: center;">Engine Mass Ballast</p> <p style="text-align: center;">Inspection and change of ballast attached to engine</p> <p style="text-align: center;">This service bulletin is cancelled, ref. ADxC-73-SB-029 issue B</p>

STANDARD

0 General

0.1 ATA Code

ATA 72 ENGINE – ballast attached at engine

0.2 Effectivity

n/a

This service bulletin is cancelled, ref. ADxC-73-SB-029 issue B